Field Service Bulletin No. 19

Order No.: DD+DIS255.01E

1 piece UST4H MA1

ADC Solo

Type 5155 / 100/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				X

Please file this document in section 13 of your technical documentation

New Hard disk introduced

The new hard disk is only available in combination with the complete plug-in storage (GS320), no separate hard disk is delivered any more.
For installation instructions, see Service Documentation (DD+DIS231.98E) Section 6.5 “Replacement of a defective Hard Disk”.

Hard disk size: 4,1 GB
Order number: CM+9.5155.1540.1

Prerequisite for using the new hard disk is Software Version SOL_1302.

If the software is not available on site you can download it from DigiNet.

printed in Germany 12 / 2001

AGFA